

# Answer Report for Coffee Machine System

- Test Cases Specification
- Test Summary Report

## Project Team

### Team 5

Latest update on:

**2016-11-30**

---

## Team Information

201111389 조정원

201210194 김정환

201211352 백대현

201211390 허윤제

## Table of Contents

1	Introduction .....	3
	1.1 Objectives .....	3
	1.2 References .....	3
2	Environmental needs .....	3
3	Answer .....	3
	3.1 Test summary report identifier .....	3
	3.2 Evaluation .....	3

## 1 Introduction

### 1.1 Objectives

본 문서는 Coffee Machine System의 unit test를 수행한 결과에 대한 report 문서이다.  
Test 요소들에 대한 test case와 test 수행 결과에 대한 내용을 담고 있다.

### 1.2 References

DS-2016SE-CM-SRS-1.0

DS-2016SE-CM-SRA-2.3

DS-2016SE-CM-SDS-1.5

T4-2016.CMS.STP-1.0

T4-2016.CMS.STR-1.0

## 2 Environmental needs

CMS를 실행하기 위한 PC – Cygwin 필요

## 3 Answer

### 3.1 Answer Summary report identifier

<Table1 Answer Result> 참조

### 3.2 Evaluation

Total defect : 4

not-in-case : 4

&lt;Table 1 Answer Result&gt;

Test case identifier	Description	Input specification	Output specification	Result
T4_STP_ver1.0 CMS.STC.002.003	*11 월 27 일 7 시 기준* 시간 6:10(과거) 추출예약 농도 100 설정을 했을 시에 이미 지나간 시간을 예약하는 것이기 때문에 Error Message 필요		not-in-case	
T4_STP_ver1.0 CMS.STC.002.004	*11 월 27 일 7 시 기준* 시간 6:40(과거) 청소예약 했을 시에 이미 지나간 시간을 예약하는 것이기 때문에 Error Message 필요		not-in-case	
T4_STP_ver1.0 CMS.STC.002.005	*11 월 27 일 7 시 기준* 시간 30:00(과거) 추출예약 농도 200, 온도 Hot 설정을 했을 시에 존재하지 않는 시간을 예약하는 것이기 때문에 Error Message 필요		not-in-case	
T4_STP_ver1.0 CMS.STC.005.000	청소 버튼 클릭시 청소가 되면서 노즐 청소와 동시에 존재하던 커피 찌꺼기 역시 청소가 되어야함.		not-in-case	